

THERESA AXFORD
Superintendent of Schools



Members of the Board

District #2
ANDY GRIFFITHS
Chairperson

District # 5
DR. SUE WOLTANSKI
Vice-Chairperson

District # 1
DARREN HORAN

District # 3
MINDY CONN

District # 4
JOHN DICK

Bid No: RFP 2023023
Name of Bid: AC Repairs and Replacements
Post Date: 11/16/2023
Notice Post Time: 2:20 p.m.

Addendum No.1

The following item has been amended from the original release format:

- Replace Section III.C.4 Sugarloaf School with the following:
 - Air Handling Units (AHU) 15 two dampers and sleeves. AHU 31,32, and 33; replace automatic outside air dampers and add duct access to allow dampers to be serviced. Dampers shall be Ruskin CD50 and shall match the existing. Replace control damper actuators. Sequence of operation shall match the existing sequence.
- Replace Section III.C.6. Horace O'Bryant School d. with the following:
 - Replace automatic damper and sleeve on AHU 601, ER301 (two dampers), and ER800 main OA damper. Replace automatic outside air dampers and add duct access to allow dampers to be serviced. Dampers shall be Ruskin CD50 and shall match the existing. Replace control damper actuators. Sequence of operation shall match the existing sequence.
- Replace Section III.C.7. Key West High School a. with the following:\ul style="list-style-type: none;">- Replace automatic dampers, sleeves, and ductwork on the following units as described below:
 - i. AHU 4-803 replace ductwork from existing OA damper to AHU
 - ii. AHU4-806 replace OA damper, sleeve, actuator, and ~5' of ductwork up to the first transition. Provide an alternate price to replace the entire section of ductwork up to the AHU.
 - iii. AHU 5-801 replace OA damper, sleeve, actuator, and ductwork up to the first transition up.

iv. Add duct access to allow dampers to be serviced. Dampers shall be Ruskin CD50 and shall match the existing. Replace control damper actuators. Sequence of operation shall match the existing sequence.